



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 12/23/2020

ID #172821

Lot #373

2011 KOMATSU HM300-2 ARTICULATED DUMP TRUCK SN: KMTHM005A29002823
CAB, AC, RADIO, 23.5R25 TIRES, ODOMETER READS: 37541, HOUR METER READS:
10679

System

General Appearance: Good

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Yes

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Hydraulic System Limited Function Check

Operational: Yes

Leaks: No

Engages: Yes

Abnormal Noise: No

Control Station

Horn: Operational

Gauges: Operational





Hour Meter: Operational

A/C & Heat



AC Functional: Operational

Heat Functional: Operational









This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.