



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 07/23/2021

ID #186865

2009 NISSAN VERSA VIN: 3N1BC13E19L477326 SEDAN

1.8L, MANUAL TRANSMISSION, CLOTH, CRUISE, AC, POWER WINDOWS, POWER
LOCKS, TIRE SIZE: 185/65R15, ODOMETER READS: 167372, ***CLUTCH GOING OUT***

System

General Appearance: Fair

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Not Tested

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Control Station

Horn: Operational

Gauges: Operational

Odometer: Operational

Warning Lights: SERVICE ENGINE LIGHT


A/C & Heat



AC Functional: Operational




Heat Functional: Operational




Other

Additional Notes: CLUTCH IS WEAK









This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.