



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 06/21/2021

ID #207318

Lot #269

2009 KOMATSU D39PX-22 SN: 3001 CRAWLER TRACTOR CAB
6 WAY BLADE, SWEEPS, REAR SCREEN, SIDE SCREENS, DRAWBAR, SBG, 26" PAD
WIDTH, HOUR METER READS: 5634

System

General Appearance: Good

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Engine Limited Function Check

Cranks & Runs: Yes



Abnormal Noise: No


Hydraulic System Limited Function Check

Operational: Yes












2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980









This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.