



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 05/28/2020

ID #166249

Lot #316

2018 MACK GU713 TANDEM AXLE DUMP TRUCK VIN: 1M2AX04C5JM038916
MACK, MP7, HP: 425, ALLISON, AUTOMATIC, CAMELBACK SUSPENSION, 230" WB,
20K FRONTS, 44K REARS, ENGINE BRAKE, DIFF LOCK, CRUISE CONTROL, DUMP
BODY MANUFACTURERS OX BODIES, 16', STEEL, DUMP BODY, SPREADER APRON,
AIR GATE, HIGH LIFT GATE, ALUMINUM FRONTS STEEL REAR WHEELS, 425/65R22.5
STEER TIRES, 11R24.5 TIRES, REAR AIR SUPPLY, HOUR METER READS: 3744,
ODOMETER READS: 68841

System

General Appearance: Good

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Not Tested

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Control Station

Horn: Operational

Gauges: Operational

Hour Meter: Operational

Odometer: Operational

A/C & Heat

AC Functional: Operational

Heat Functional: Operational








2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980











2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980










BY MACK TRUCKS, INC.	GVWR 28123	KG (62000)	LE
038916	GAWR - FRONT AXLE: 8165	KG (18000)	LE
	GAWR - 1ST INTERMEDIATE AXLE: 9979	KG (22000)	LE
	GAWR - 2ND INTERMEDIATE AXLE: 0	KG (0)	LE
	GAWR - 3RD INTERMEDIATE AXLE: 0	KG (0)	LE
	GAWR - 4TH INTERMEDIATE AXLE: 0	KG (0)	LE
	GAWR - 5TH INTERMEDIATE AXLE: 0	KG (0)	LE
	GAWR - REAR AXLE: 9979	KG (22000)	LE

2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980



This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.