



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 05/28/2020

ID #166246

Lot #314

2018 MACK GU713 TANDEM AXLE DUMP TRUCK VIN: 1M2AX04C1JM038914
MACK MP7, HP: 425, ALLISON AUTOMATIC, CAMELBACK SUSPENSION, 230" WB, 20K
FRONTS, 44K REARS, ENGINE BRAKE, DIFF LOCK, CRUISE CONTROL, OX BODIES 16'
STEEL DUMP BODY, SPREADER APRON, MANUAL GATE, HIGH LIFT GATE,
ALUMINUM FRONTS STEEL REAR WHEELS, 425/65R22.5 STEER TIRES, 11R24.5
TIRES, REAR AIR SUPPLY, HOUR METER READS: 3750, ODOMETER READS: 57428

System

General Appearance: Good

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Not Tested

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Control Station

Horn: Operational

Gauges: Operational

Hour Meter: Operational

Odometer: Operational

Warning Lights: CHECK ENGINE

A/C & Heat




AC Functional: Operational





Heat Functional: Operational





2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980











2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980



This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.