



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 08/04/2020

ID #174180

Lot #130

2014 KOMATSU D65PX-17 SN: KMT0D117H01002337 CRAWLER TRACTOR
CAB, A/C, RADIO, REAR VIEW CAMERA, 6 WAY BLADE, MULTI SHANK RIPPER,
KOMATSU PLUS, 30" SBG, HOUR METER READS: 3214

System

General Appearance: Good

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Not Tested

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Hydraulic System Limited Function Check

Operational: Yes

Leaks: No

Engages: Yes

Abnormal Noise: No

Control Station

Horn: Operational

Gauges: Operational

Hour Meter: Operational

A/C & Heat

AC Functional: Operational


Heat Functional: Operational

Other

Other Leaks: Not Tested







2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980








2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980






2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980









This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.