



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 08/04/2020

ID #167168

Lot #134

2012 KOMATSU D39PX-22 SN: KMT0D108H01003594 CRAWLER TRACTOR
CANOPY, 6 WAY BLADE, SWEEPS, REAR SCREEN, SIDE SCREENS, DRAWBAR, 24"
PADS, SBG, HOUR METER READS: 4073

System

General Appearance: Good

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Not Tested

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Hydraulic System Limited Function Check

Operational: Yes

Leaks: No

Engages: Yes

Abnormal Noise: No

Control Station

Horn: Operational

Gauges: Operational



Hour Meter: Operational







Odometer: Not Tested



Other


Other Leaks: Not Tested














2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980



This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.