



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:  
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 10/06/2020

**ID #152841**

**Lot #7**

1999 KOMATSU WB140 UTILITY 4X4 LOADER BACKHOE SN: FK1 140F10279  
CAB, GP BKT, AUX HYD, 36" BUCKET, 4 CYL YANMAR DIESEL ENGINE, OUTRIGGERS,  
FRONT TIRE SIZE 14X17.5NHS, REAR TIRE SIZE 19.5L-24, HOUR METER READS:  
4737

### **System**

**General Appearance:** Good

### **Transmission Limited Function Check**

**Engages Forward/Reverse:** Yes

**Shifts All Gears:** Yes

**Abnormal Noise:** No

### **Brakes Limited Function Check**

**Operational:** Yes

### **Engine Limited Function Check**

**Cranks & Runs:** Yes

**Abnormal Noise:** No

### **Hydraulic System Limited Function Check**

**Leaks:** Yes- FRONT RIGHT BUCKET CYLINDER, STEERING CYLINDER, SWING CYLINDER LEAK ON  
LEFT SIDE

**Engages:** Yes

**Abnormal Noise:** No

### **Control Station**

**Horn:** Operational

**Gauges:** Operational



**Hour Meter:** Operational

### **A/C & Heat**


**AC Functional:** Non-Operational


























2236 Hwy 49 | Brooklyn, MS 39425 | Phone:  
601-450-6200 | Fax: 601-450-4980



This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.