



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 11/02/2020

ID #163695

Lot #454

1984 AUTOCAR TANDEM AXLE WATER TRUCK VIN:
CATERPILLAR, EATON FULLER, 10 SPEED, SPRING SUSPENSION, 224 " WB, 1000
GALLON CAPACITY (APPROX), FRONT, SIDE, REAR DISCHARGE, 14K FRONTS, 40K
REARS, STEEL DISC WHEELS, 385/65R22.5 STEER TIRES, 11R22.5 TIRES, HOUR
METER READS: 8751, ODOMETER READS: 262862, *** VIN: OBL, TITLE STATES: 1984
AUTOCAR, VIN:1WBUCCCG4EU096591 ***

System

General Appearance: Fair

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Not Tested

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Hydraulic System Limited Function Check

Operational: Not Tested

Leaks: Not Tested

Engages: Not Tested

Abnormal Noise: Not Tested

Control Station

Horn: Non-Operational

Gauges: Operational

Hour Meter: Operational

Odometer: Operational

A/C & Heat

AC Functional: Not Tested

Heat Functional: Not Tested



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980


Heat Functional: NOT TESTED


Other





Other Leaks: Yes - LEAKING OIL FROM ENGINE BLOCK
















2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980



This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.