



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 12/08/2020

ID #124815

2015 CHEVROLET SILVERADO 1500 CREW CAB 4X4 PICKUP VIN:

3GCUKREC0FG182354

VORTEC 5.3L 8 CYL GAS ENGINE, AUTOMATIC TRANSMISSION, CRUISE, AC/HEAT, TOOL BOX, BED LINER, RUNNING BOARDS, AUTO WINDOWS/LOCKS, WORK LIGHTS, TIRES 265/65R18, ODOMETER READS: 206514, ***TRANSMISSION ISSUES, WON'T GO INTO REVERSE & HARD TIME SHIFTING IN DRIVE***

System

General Appearance: Excellent

Transmission Limited Function Check

Engages Forward/Reverse: No - WILL NOT GO IN REVERSE

Shifts All Gears: No - WILL NOT GO IN REVERSE

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Control Station

Horn: Operational

Gauges: Operational

Odometer: Operational

A/C & Heat

AC Functional: Operational

Heat Functional: Operational

Other

Additional Notes: NO MAJOR ISSUES OTHER THAN TRANSMISSION WILL NOT GO IN REVERSE






2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980










2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980





2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980





		MFD BY GENERAL MOTORS DE MEXICO, S. DE R.L. DE C.V. 10/14			
GVWR		GAWR FRT		GAWR RR	
3286 KG		1792 KG		1792 KG	
7200 LB		3950 LB		3950 LB	
					
THIS VEHICLE CONFORMS TO ALL APPLICABLE U.S. FEDERAL MOTOR VEHICLE SAFETY STANDARDS IN EFFECT ON THE DATE OF MANUFACTURE SHOWN ABOVE.					
3GCCUKRECOFG182354				TYPE: TRUCK	
MODEL: K15543					
KG/M	TIRE SIZE	SPEED RTG	RIM	COLD TIRE PRESSURE	
FRT	P265/65R18	T	18X8.5J	240KPA(35PSI)	
RR	P265/65R18	T	18X8.5J	240KPA(35PSI)	
SPA	P265/70R17	S	17X7J	240KPA(35PSI)	
SEE OWNER'S MANUAL  FOR MORE INFORMATION.					

This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.