



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:  
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 03/02/2021

**ID #187526**

**Lot #11628**

2020 MACK GR64F GRANITE TRI-AXLE DUMP TRUCK VIN: 1M2GR4GC4LM016772  
MACK MP8, HP: 455, ALLISON AUTOMATIC, CAMELBACK SUSPENSION, 228" WB, 20K  
FRONTS, 46K REARS, AIR LIFT, ENGINE BRAKE, DIFF LOCK, REAR AIR SUPPLY,  
CRUISE CONTROL, OX BODIES 16' STEEL DUMP BODY, SPREADER APRON, TARP,  
AIR GATE, HIGH LIFT GATE, ALUMINUM DISC WHEELS, 425/65R22.5 STEER TIRES,  
11R24.5 TIRES, PINTLE HITCH, 11R22.5 LIFT W/STEEL WHEELS, HOUR METER  
READS: 862, ODOMETER READS: 19434, \*\*\*COUNTY OWNED\*\*\*

### **System**

**General Appearance:** Excellent

### **Transmission Limited Function Check**

**Engages Forward/Reverse:** Yes

**Shifts All Gears:** Not Tested

**Abnormal Noise:** No

### **Brakes Limited Function Check**

**Operational:** Yes

### **Engine Limited Function Check**

**Cranks & Runs:** Yes

**Abnormal Noise:** No

### **Hydraulic System Limited Function Check**

**Operational:** Yes

**Leaks:** No

**Engages:** Yes

**Abnormal Noise:** No

### **Control Station**

**Horn:** Operational

**Gauges:** Operational

**Hour Meter:** Operational

**Odometer:** Operational

### **A/C & Heat**










2236 Hwy 49 | Brooklyn, MS 39425 | Phone:  
601-450-6200 | Fax: 601-450-4980


**AC Functional:** Operational  
**Heat Functional:** Operational


**Other**  
**Other Leaks:** No











This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.