



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 03/02/2021

ID #187528

Lot #11630

2020 MACK GR64F GRANITE TRI-AXLE DUMP TRUCK VIN: 1M2GR4GC2LM016771
MACK MP8, HP: 455, ALLISON AUTOMATIC, CAMELBACK SUSPENSION, 228" WB, 20K
FRONTS, 46K REARS, AIR LIFT, ENGINE BRAKE, DIFF LOCK, REAR AIR SUPPLY,
CRUISE CONTROL, OX BODIES 16' STEEL DUMP BODY, SPREADER APRON, TARP,
AIR GATE, HIGH LIFT GATE, ALUMINUM DISC WHEELS, 425/65R22.5 STEER TIRES,
11R24.5 TIRES, PINTLE HITCH, 11R22.5 LIFT W/STEEL WHEELS, HOUR METER
READS: 988, ODOMETER READS: 19440, ***COUNTY OWNED***

System

General Appearance: Excellent

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Not Tested

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Hydraulic System Limited Function Check

Operational: Yes

Leaks: No

Engages: Yes

Abnormal Noise: No

Control Station

Horn: Operational

Gauges: Operational

Hour Meter: Operational

Odometer: Operational

A/C & Heat








2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980





AC Functional: Operational
Heat Functional: Operational



Other
Other Leaks: No













2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980



This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.