



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 03/20/2021

ID #178279

Lot #372

2010 HAMM HD110HV SN: H181640

TANDEM VIBRATORY ROLLER, CANOPY, WATER SPRAY SYSTEM

System

General Appearance: Fair

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Yes

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Hydraulic System Limited Function Check

Operational: Yes

Engages: Yes

Control Station

Horn: Operational

Gauges: Operational


Hour Meter: Operational











This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.