



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 05/15/2021

ID #205045

KOMATSU D37P-5 SN: 3842 CRAWLER TRACTOR
CANOPY, 6 WAY BLADE, SWEEPS, REAR SCREEN, DRAWBAR, 24" PADS, SBG, HOUR
METER READS: 1533, ***INTERMITTENT TRACKING ISSUES***

System

General Appearance: Good

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Hydraulic System Limited Function Check

Operational: Yes

Leaks: No

Engages: Yes

Abnormal Noise: No

Control Station


Gauges: Non-Operational

Hour Meter: Operational




2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980













This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.