



2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

Item Evaluated on 05/18/2021

ID #205187

Lot #418

2015 VOLVO VNL VIN: 4V4NC9EH6FN175319 TANDEM AXLE TRUCK TRACTOR
VOLVO, D13, AUTOMATIC, AIR RIDE SUSPENSION, 240 " WB, C/A: 118", 12K FRONTS,
38K REARS, STATIONARY FIFTH WHEEL, DIFF LOCK, CRUISE CONTROL, APU,
SLEEPER SIZE 56", ALUM DISC WHEELS, 295/75R22.5 TIRES, HOUR METER READS:
10225, ODOMETER READS: 369502

System

General Appearance: Good

Transmission Limited Function Check

Engages Forward/Reverse: Yes

Shifts All Gears: Yes

Abnormal Noise: No

Brakes Limited Function Check

Operational: Yes

Engine Limited Function Check

Cranks & Runs: Yes

Abnormal Noise: No

Hydraulic System Limited Function Check

Operational: Not Tested

Leaks: No

Engages: Not Tested

Abnormal Noise: No

Control Station

Horn: Operational

Gauges: Operational

Hour Meter: Operational

Odometer: Operational

A/C & Heat

AC Functional: Operational

Heat Functional: Operational






2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980


Other

Other Leaks: No











2236 Hwy 49 | Brooklyn, MS 39425 | Phone:
601-450-6200 | Fax: 601-450-4980

ANNUAL VEHICLE INSPECTION REPORT

VEHICLE HISTORY RECORD

DATE: 5-17-2021

INSPECTOR: [Signature]

VEHICLE IDENTIFICATION: [Redacted]

VEHICLE COMPONENTS INSPECTED

NO.	ITEM	YES	NO
1	1. BRAKE SYSTEM		
2	2. COUPLING DEVICES		
3	3. EXHAUST SYSTEM		
4	4. ENGINE OIL		
5	5. LIGHTING DEVICES		
6	6. SAFE LOADING		
7	7. STEERING MECHANISM		
8	8. SUSPENSION		
9	9. TIRE		
10	10. TIRES		
11	11. WHEELS AND RIMS		
12	12. WINDSHIELD GLAZING		
13	13. WINDSHIELD WIPERS		
14	14. WORKS/COACH SEATS		
15	15. OTHER		

CERTIFICATION: THIS VEHICLE HAS PASSED ALL THE INSPECTION ITEMS FOR THE ANNUAL VEHICLE INSPECTION IN ACCORDANCE WITH 49 CFR PART 395.

ORIGINAL

3128 (Rev. 07/16)

This report is designed to disclose any obvious and known problems observed during a limited function check. This report was not generated by a certified technician. This report is not designed to uncover all defects. It is in no way a guarantee of condition or warranty. The buyer is buying at their own risk. Jeff Martin Auctioneers strongly encourages in person inspections before bidding.